### \*What is Cost Sharing?

Cost Sharing is financial assistance to pay for a portion of the project. The Winnebago County Land and Water Conservation Department has state and local funding sources used for cost sharing the installation of conservation practices, such as, well abandonment projects.



Well owners may be eligible to receive 70% of the total cost to properly abandon a well to a maximum of \$1,000.00

ahandonment projects need

per project.

Well abandonment projects need to be completed by a licensed well driller or pump installer to be eligible for cost sharing.



Bentonite chips being poured into a well during abandonment.



Winnebago County

FOR MORE INFORMATION
ABOUT WELL
ABANDONMENT
PROJECTS CONTACT:

Winnebago County
Land & Water Conservation Department
625 E. County Road Y, Suite 100
Oshkosh, WI 54901-8131

Phone: (920) 232-1950 (920) 727-8642 Fax: (920) 424-1277 Website: http://wclwcd.org



## Winnebago County

Land & Water Conservation Department

### Well Abandonment Cost Share Program



# Well Abandonment Cost Share\* Program

#### Why Should I Properly Abandon My Old Well?

unused are at risk of having concan develop cracks in the steel casthe groundwater. Old drilled wells taminants enter into them and into Old wells that are left open and/or groundwater. Once prevent contamidoes not provide a good barrier to possible to remove is difficult, if not imthe groundwater, it contaminants reach nants from reaching lined with brick or field stone which through. Old dug wells were often ing that can let contaminants

them. Often the contamination will migrate to other wells drawing water from that aquifer.

Old and unused wells may also pose a safety hazard. Old dug wells can be 6 feet across and 50 feet deep or

Old and unused wells may also pose a safety hazard. Old dug wells can be 6 feet across and 50 feet deep or deeper. Serious injury or worse could result if a person or animal fell into an old well.

## How Do I Get Started?

The following describes the steps landowners must follow in order to receive cost sharing for a well abandonment project under this prodoment

- The well owner applies for cost sharing from Winnebago County LWCD.
- 2) The well owner requests a cost estimate for the well abandonment project from a Licensed Well Driller or Pump Installer (service provider). NOTE: If the first estimate exceeds \$500.00, a second estimate is required.
- 3) A copy of the cost estimate is submitted to the Winnebago County LWCD for review. The LWCD reviews the project and determines eligibility for cost sharing.
- 4) If the project is eligible for cost sharing, a "Cost Share Agreement" (CSA) must be signed by all necessary parties and approved before any work is done on the well abandonment pro-

- ject. Well owners that do not have a signed and approved CSA prior to beginning their project will be denied cost sharing.
- the well owner pays the service provider in full and requests a signed and dated receipt indicating the amount paid or the invoice marked "Paid in Full" signed and dated. The service provider must also properly complete and sign a WDNR Well Abandonment Form 3300-005 and give a copy to the well owner.
- The well owner submits these documents to the LWCD for review and reimbursement in accordance with the CSA.

FOR MORE INFORMATION ABOUT WELL ABANDONMENT PROJECTS CONTACT:

Winnebago County
Land & Water Conservation Department
625 E. County Road Y, Suite 100
Oshkosh, WI 54901-8131

Phone: (920) 232-1950 (920) 727-8642 Fax: (920) 424-1277 Website: http://wclwcd.org