To whom it may concern:

I am writing about an insurance reimbursement due to a road hazard. On Thursday, February 21, 2013 at approximately 1:30pm, I was driving south on 41, getting onto 441-10 east going around the curve. There was a large pot hole when I was coming around the corner with a chunk of cement standing straight up in pot hole. Do to road conditions I was unable to avoid the hole and chunk of cement which caused damage to my car.

I would like to be reimbursed for the repair costs to my car. I had to replace the tire, rim and rear knuckle and the total of the repairs are as follows. The cost to replace the damaged rim is \$150.00. The tire and instillation cost \$119.92; the repairs to the chassis were \$215.27. The total was \$485.94 for my car to be back to the previous condition.

The highway commission's office instructed me to submit my claim to you to be processed. Please feel free to contact me with any questions or additional information you may require. Thank you for your time and I look forward to hearing from you soon.

Sincerely,

Kristi Kaczrouske

Kristi Kaczrouske


1273 Green Acres Lane

Neenah, WI 54956

920-606-8846 (Cell)

KLK11690@yahoo.com (email)

List Kacon 2





POMP'S TIRE SERVICE, INC.

REMITTANCE ADDRESS: POMP'S TIRE SERVICE, INC. ATTN: AR DEPARTMENT P.O. BOX 1630 GREEN BAY, WI 54305-1630

POMP'S TIRE-OSHKOSH 2180 S WASHBURN ST

INVOICE #: 270008657

PAGE:

1

OSHKOSH, WI 54904

920/235-7590

CUSTOMER:

RICHARD ROSE

647 E ONTARIO ST

482

OMRO WI 54963

CREATED BY

RAMIRO

SALESMAN: RAMIRO CONTRERAS

LICENSE: NO-VEHICLE

INVOICE DATE: 03/12/13

TERMS: DUE ON DELIVERY

PRODUCT	MECHANIC	QUANTITY	PRICE	F.E.T.	EXTENSION
225/50VR16 FIERCE INSTINCT\$		1	116.70		116.70
PASSENGER SPIN BALANCE	270	9 1.0	10.00		10.00
RUBBER SNAP IN VALVE PVALV		1	2.50		2.50
PASSENGER SCRAP DISPOSAL FE	E	1	2.50		2.50
PDISP PREFERRED CUSTOMER DISCOUNT		-1	17.50		-17.50
415L				יוו אל ייוול אווי	CAME TITME

TIRE WAS DAMAGED AT SAME TIME WHEEL WAS DAMAGED APPEARED TO HAVE AT SAME TIME THAT TIRE HIT LARGE PIECE OF CONCRETE APPROX . COST OF USED WHEEL \$ 150.00

> MERCHANDISE: LABOR: OTHER:

10.00 2.50

101.70

SALES TAX: INVOICE TOTAL:

5.72 119.92

VISA/MASTERCARD

119.92

NEW ESTIMATE

LUG NUT'S SHOULD BE RE-TORQUED AFTER 50 TO 100 MILES.X

Signature

And the same of th Printed Name

A finance charge of 1.5% per month (18% APR) will be added to the unpaid balance after 30 days.

CUSTOMER ESTIMATE SELECTION

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.

- 1. I request an estimate in writing before you begin repairs.
- 2. Please proceed with repairs but call me before continuing if price will exceed S_____
- 3. I do not want an estimate.

Do you want the replaced parts you are entitled to? TYES TO ESTIMATED PRICE OF REPAIRS This vehicle received without face to face customer contact.

ADDITIONAL WORK AUTHORIZED BY:

A.M.

CUSTOMER SIGNATURE X _____

causes beyond your control.

Hereby authorize the below repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs

thereto. You will not be held responsible for loss or damage to vahicle or articles left in vehicle

in case of fire, theft, accident, damage from freezing due to lack of anti-freeze or any other

MAIN TIRE AND MAINTENANCE

1121 E MAIN ST

Omro, WI 54963 Shop Phone: (920) 685-5553 Invoice

72583

Estimate Ref #72,461

Date Printed: 02/25/2013 Printed Time: 5:02 pm

Time Promised:

Hat/Ref:

KACZROUSKE, KRISTI

647 E. ONTARIO

Omro, WI 54963

Home: (920) 606-8846 Cell:

Unit #:

License: 283-JBN

1999 OLDSMOBILE ALERO V6 3.4L 207CID FI GAS N E

VIN: 1G3NF52E6XC411387

Mileage In: 149,258

Date Written:

02/25/2013

Mileage Out: 149,258

Written By: Jerry

DOM:

Save Old Parts: No

Gell.					
Job Name	Description	Technician	Qty	List	Extended
Job #1	HIT SOMETHING ON THE				
	ROADCHECK FOR DAMAGE				
Labor 1	Work Requested - HIT SOMETHIN	IG ON THE	1.00	81.50	81.50
	ROADCHECK FOR DAMAGE.				
Work Performed - TEST DRIVE	AND INSPECT. LEFT REAR LATERAL	LINK BENT. REPLACE.	4.00	45.69	15.00
Part 22606764	REAR LATERAL LINKLEFTE	3A	1.00	45.69	45.69
Note/Title					
P225/50R16 FUSION VRI TIRE	= NOT AVAILABLE. DORAL = \$131.32	TOTAL			1
					200
THRUST ANGLE ALIGNMENT	CHECK ALL SUSPENSION AND		2		
THROST ANGLE ALIGNMENT	STEERING PARTS FOR W				Service on the
Labor 1	Work Requested - ALIGNMENT		1.00	69.95	69.95
Work Performed - ALIGN 4 WHE	EELSRECOMMEND NEW STRUT	S (REAR ARE MOST WO	RN)		
VIOINT CHOILING TIEFORT THE		V-0.			

Payment Date	Type	Method	Amount	
2/25/2013	Cash	Payment Totals:	215.27 \$215.27	
				appear of the second se
	*			

Parts: \$45.69 Labor: \$151.45 \$0.00 Sublet: \$0.00 Misc: Hazmat: \$0.00 \$7.89 Supplies:

\$10.24

Invoice Total: \$215.27 215.27 Less Paid:

Tax Total:

Balance Due: \$0.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Time _ Authorized By _