



Winnebago County

Office of the County Clerk

The Wave of the Future

OSHKOSH (920) 236-4890

FOX CITIES (920) 727-2880

FAX (920) 303-3025

E-mail: countyclerk@co.winnebago.wi.us

NOTICE OF CLAIM

DATE: July 13, 2020
TO: Doug Petraszak, Linda Staffaroni and Joan Lowe
FROM: Sue Ertmer
RE: Claim from Terry Babcock

Mr. Babcock's claim for damages to his 2003 Chevrolet Truck from improper sealing operation on Highway 116 by the Winnebago County Highway Department will be presented to the County Board at their July 21, 2020 meeting.

attachments

Winnebago County Clerk,

Attached is the Preliminary Estimate from In-Line Auto Body, Inc. in the amount of \$2,592.24 for the repairs needed to my 2003 Chevrolet Silverado Truck. This stems from the improper sealing operation that was preformed by Winnebago County Highway Department on Tuesday, June 16, 2020 on Hwy 116 West of Hwy 45.

This is not the result of failing to slow down, but the fact of the uncovered asphalt oil spray that stuck to the tires and sprayed the asphalt oil and 5/16" stone chips onto the outside body of the truck causing paint chipping and asphalt sprayed body.

The chipped clear coat, chipped paint and primer all the way to the bare metal will be the result of rust to this truck that was refinish in July of 2019 if this is not professionally repainted.

Please review the attached photos of the damage, before and after asphalt oil was removed and the email that was sent to the county highway department immediately after the damage accrued.

This estimate does not compensate of the hours of cleanup to the truck and rims that has been already done.

Please let me know the results of your review by contacting via:

Phone: (920) 420-8397

Email: tbabcock@ntd.net


Thank you,

Terry Babcock

9162 County Road D.

Winneconne, WI. 54986


7/10/20



Fwd: Website Feedback

From: Cody Babcock <cody.2babcock@gmail.com>

Date: 06/26/2020 06:13PM

To: tbabcock@ntd.net

Sent from my iPhone

Begin forwarded message:

From: "Groth, Jonathan" <JGroth@co.winnebago.wi.us>

Date: June 17, 2020 at 11:52:09 AM CDT

To: "cody.2babcock@gmail.com" <cody.2babcock@gmail.com>

Cc: Hwy <Hwy@co.winnebago.wi.us>, "Palonen, Raymond" <RPalonen@co.winnebago.wi.us>, "Averkamp, Dan" <DAverkamp@co.winnebago.wi.us>

Subject: RE: Website Feedback

Cody-

Signing on STH 116 was placed according to Wisconsin Work Zone standards. There were ROAD WORK, LOOSE GRAVEL, ONE LANE ROAD, FLAGGER SYMBOL, and NO CENTER LINE signs in place.

The issue yesterday was a result of drivers failing to slow down for road conditions. Asphalt seals consist of a thin layer of sprayed asphalt which is then immediately covered with a 5/16" stone chip. Problems occur when drivers no longer operate at reasonable speeds and the cover stone chips begin to roll over in the asphalt, resulting in cover chips adhering to vehicle tires and then being thrown from the roadway. Twenty miles of County roadway had been previously sealed without this occurring.

There are asphalt emulsifiers available which safely dissolve asphalt residue. These can be found at home building stores such as Fleet Farm or Menards. (usually found in the automotive section of the store). These are usually citrus or soy base products which will clean up with mild soap and water.(SIMPLE GREEN is an effective parts cleaner carried by Fleet Farm) Automotive supply stores or body shops also carry effective asphalt cleaners.

If you feel that you should receive compensation for cleanup or damage to vehicles, you can submit claims to the following address:

WINNEBAGO COUNTY CLERK
P.O. Box 2808
Oshkosh, WI 54903-2808

Include a detailed description of the incident including date, time location, dollar amount claimed along with any other pertinent documentation, including photographs.

Jon Groth
Winnebago County Highway Supt.
901 W. County Road Y
Oshkosh, WI 54901>
Office:(920)232-1745

-----Original Message-----

From: Hwy
Sent: Wednesday, June 17, 2020 8:57 AM
To: Palonen, Raymond <RPalonen@co.winnebago.wi.us>; Groth, Jonathan <JGroth@co.winnebago.wi.us>; Averkamp, Dan <DAverkamp@co.winnebago.wi.us>
Subject: FW: Website Feedback

-----Original Message-----

From: Webmaster
Sent: Wednesday, June 17, 2020 8:44 AM
Subject: FW: Website Feedback

Just forwarding this along, let me know if this is not the right department for this.

Thanks,
Webmaster

-----Original Message-----

From: webmaster@co.winnebago.wi.us <webmaster@co.winnebago.wi.us>
Sent: Tuesday, June 16, 2020 6:14 PM
To: Webmaster <Webmaster@co.winnebago.wi.us>
Subject: Website Feedback

Submitted on Tuesday, June 16, 2020 - 6:13pm Submitted values are:

Your e-mail address: cody.2babcock@gmail.com Your Name: Cody Babcock
Subject: Tar and gravel.

Message: Taking the off ramp south of 10 not expecting loose gravel on 116 my father and friends have a lot of paint damage and tar covered trucks. Because maybe their was no road work ahead signs coming off the ramps to at least warn them. Poor traffic control. Should be ashamed. Now what are they going to do with their damaged vehicles, pay for it themselves? I have picture to prove.

In-Line Auto Body, Inc.
106 East Tennessee Avenue
Oshkosh, WI 54901
Phone: (920) 232-7222 | Fax: (920) 232-8469

*** PRELIMINARY ESTIMATE ***

07/01/2020 02:25 PM

Owner

Owner: Terry Babcock
Address: 9162 Cty. Rd. D
City State Zip: Winneconne, WI 54986

Work/Day: (920)420-8397
FAX:

Inspection

Inspection Date: 07/01/2020 02:25 PM

Inspection Type:

Repairer

Repairer: Kurt Hinz
City State Zip: WI

Contact:
FAX:

Target Complete Date/Time:

Days To Repair: 9

Remarks

ALL REPAIRS AND REFINISH IS ESTIMATED FROM THE BODY LINE DOWN

Vehicle

OEM Part Price Quote ID: ****

2003 Chevrolet Silverado K1500 LS 4 DR Ext Cab Short Bed
8cyl Gasoline 5.3
4 Speed Automatic

Lic Expire:
Prod Date: 11/2002
Veh Insp# :
Condition:

Ext. Color:
Ext. Paint Code:

VIN: 2GCEK19T731216410
Mileage:
Mileage Type: Actual
Code: U8033D
Int. Color: Dark Charcoal w/Custom Cloth
Seat T
Int. Trim Code: 69D

Options - AudaVIN Information Received

4-Wheel Drive
Aluminum/Alloy Wheels
Automatic Dimming Mirror
Bucket Seats
Chrome Step Bumper
Dual Airbags
Fog Lights
Hinged Fourth Door
Leather Steering Wheel
Power Brakes
Power Steering
Rear Bench Seat

Air Conditioning
Anti-Lock Brakes
Automatic Trans
Camper/Towing Package
Compact Disc W/Tape
Electronic Transfer Case
Heated Power Mirrors
Intermittent Wipers
Lighted Entry System
Power Door Locks
Power Windows
Rear Window Defroster

Alarm System
Auto Locking Hubs (4WD)
Bose Sound System
Center Console
Cruise Control
Fender Flares
Heavy Duty Cooling
Keyless Entry System
Overhead Console
Power Drivers Seat
Privacy Glass
Skid Plates

Tachometer
Trailer Hitch

Tilt Steering Wheel
Tutone Paint

Tinted Glass
Velour/Cloth Seats

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R		
Front Body And Windshield												
1	RI	63		Flare,Wheel Opening LT	R & I Assembly				0.5	SM		
2	RI	64		Flare,Wheel Opening RT	R & I Assembly				0.5	SM		
Cab And Components												
3	IT	627		Panel,Rocker LT	Partial Repair				2.0*	SM		
4	L	627		Panel,Rocker LT	Refinish				1.1	RF		
					1.1 Surface							
5	CG	627		Panel,Rocker LT	Chipguard				0.3	RF		
6	IT	628		Panel,Rocker RT	Partial Repair				2.0*	SM		
7	L	628		Panel,Rocker RT	Refinish				1.1	RF		
					1.1 Surface							
8	CG	628		Panel,Rocker RT	Chipguard				0.2	RF		
Front Doors												
9	I	207		Door Shell,Front LT	Repair				2.0*	SM		
10	L	207		Door Shell,Front LT	Refinish				2.0*	RF		
					2.0 Surface							
11	I	208		Door Shell,Front RT	Repair				2.0*	SM		
12	L	208		Door Shell,Front RT	Refinish				2.0*	RF		
					2.0 Surface							
Rear Doors												
13	I	287		Door Shell,Rear LT	Repair				1.0*	SM		
14	L	287		Door Shell,Rear LT	Refinish				1.5*	RF		
					1.5 Surface							
15	I	288		Door Shell,Rear RT	Repair				1.0*	SM		
16	L	288		Door Shell,Rear RT	Refinish				1.5*	RF		
					1.5 Surface							
Bed												
17	I	497		Panel,Bedside LT	Repair				1.5*	SM		
18	L	497		Panel,Bedside LT	Refinish				2.5*	RF		
					2.5 Surface							
				>> Refinish Lower Areas Only								
19	I	498		Panel,Bedside RT	Repair				1.5*	SM		
20	L	498		Panel,Bedside RT	Refinish				2.5*	RF		
					2.5 Surface							
21	RI	575		Flare,Wheel Opening LT	R & I Assembly				0.5	SM		
22	RI	576		Flare,Wheel Opening RT	R & I Assembly				0.5	SM		

Manual Entries

23	EC	M17		Cover Car Exterior	Replace Economy	\$10.00*				RF
				23 Items						

Estimate Total & Entries

Other Parts						\$10.00				
Paint & Materials				14.7 Hours @ \$42.00		\$617.40				
Parts & Material Total									\$627.40	
Tax on Parts & Material				@ 5.000%					\$31.37	

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$62.00	2.0	13.0	15.0	\$930.00
Mech/Elec (ME)	\$80.00				
Frame (FR)	\$70.00				
Refinish (RF)	\$62.00	14.7		14.7	\$911.40
Labor Total				29.7 Hours	\$1,841.40
Tax on Labor		@ 5.000%			\$92.07
Gross Total					\$2,592.24
Net Total					\$2,592.24

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 54901 Audatex Host
 OEM Part Prices DT 07/01/2020 02:25 PM EstimateID 707674340690239488 QuoteID ****
 SPPL Yes Zip Code: 54901 Default
 Rate Name Default

Audatex Estimating 8.0.818 Update 2 ES 07/01/2020 02:38 PM REL 8.0.818 Update 2 DT 06/01/2020
 © 2020 Audatex North America, Inc.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc.
 AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.















