



INSURANCE & FINANCIAL SERVICES

September 19, 2012

Winnebago County Clerk Office  
PO Box 2808  
Oshkosh WI 54903-2808

Attn: Sue Ertmer

To Whom It May Concern:


Enclosed is a repair estimate from our client Randy Boyce, owner of Ready Builders in the amount of \$4053.35 for damages caused to his vehicle while parked at the Winnebago County Landfill. According to the enclosed police report, a vehicle owned by Winnebago County backed into him on 8/30/12.

Please contact Randy Boyce at 920-420-4430 to settle this claim.

Best Regards,

A handwritten signature in black ink, appearing to read "Tom Pupeter".

Thomas J. Pupeter, CPCU



303 PEARL AVENUE P.O. BOX 3387 OSHKOSH, WI 54903-3387

920-235-6461 800-236-1012 FAX 920-235-3186

[www.thomasinsurancegroup.com](http://www.thomasinsurancegroup.com)

POLICE #  
ACCIDENT # 12-30947

<input type="checkbox"/> Reportable Accident		<input type="checkbox"/> On Emergency		<input type="checkbox"/> Amended		DOT Document Number FZ6ZNV5		Document Override Number	
Agency Accident Number 12-30947				Police Number					
4 - Accident Date 08/30/2012		5 - Time of Accident (Military Time) 0656		6 - Total Units 02		7 - Total Injured 00		8 - Total Killed 00	
2 - County WINNEBAGO - 70		3 - Municipality OSHKOSH - 55 CITY		11 - Accident Location PRIVATE PROPERTY					
14 - On Hwy No.		14 - On Street Name PRIVATE PROPERTY		14 - Bus/Fmt/Rmp		15 - Est. Dist		15 - Hwy. Dir	
16 - Fr/At Hwy No.		16 - From/At Street Name 100 W CTH Y		16 - Business/Frontage/Ramp					
17 - Structure Type		17 - Structure Number		12 - Latitude		13 - Longitude			
80 - First Harmful Event MOTOR VEHICLE IN TRANSPORT				93 - Manner of Collision REAR-END					
112 - Access Control NO CONTROL		113 - Road Curvature STRAIGHT		113 - Road Terrain LEVEL/FLAT		Surface Type BLACKTOP (BITUMINOUS) - 2			
115 - Traffic Way PARKING LOT OR PRIVATE PROPERTY									
117 - Relation To Roadway PARKING LOT OR PRIVATE PROPERTY									
114 - Light Condition DAYLIGHT		116 - Road Surface Condition DRY		118 - Weather CLEAR					
<input type="checkbox"/> Hit and Run		<input type="checkbox"/> Government Property		<input type="checkbox"/> Fire		<input type="checkbox"/> Photos Taken		<input type="checkbox"/> Trailer or Towed	
<input checked="" type="checkbox"/> Truck, Bus, or Hazardous Materials		<input type="checkbox"/> Load Spillage		<input type="checkbox"/> Construction Zone		<input type="checkbox"/> Names Exchanged			
101 <input type="checkbox"/> Supplemental Reports		102 <input type="checkbox"/> Witness Statements		103 <input type="checkbox"/> Measurements Taken		79 - E M S Number			

Operator/Pedestrian

Unit Status		81 - Most Harmful Event: Collision With MOTOR VEHICLE IN TRANSPORT		23 - Dir Of Travel NORTH		24 - Speed Limit N/A	
36 - Operating as Classified D CLASS		37 - Endorsements		35 <input type="checkbox"/> Operating Commercial Motor Vehicle			
29 - Driver's License Number B2007356620301		30 - State WI		31 - Expiration Year 2017		34 - On Duty Accident	
25 - Operator/Pedestrian Last Name BOYCE		25 - First Name RANDY		25 - Middle Initial P		25 - Suffix	
32 - Date Of Birth 06/03/1966		33 - Sex MALE					
26 - Address Street & Number W2834 S COUNTY ROAD A						26 - PO Box	
27 - City PINE RIVER		27 - State WI		27 - Zip Code 54965		28 - Telephone Number (920) 420-4430 EXT.	
39 - Seat Position FRONT-SEAT-LEFT-SIDE-(MC/BIKE DRIVER, TRAIN CONDUCTOR)				40 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED			
38 - Injury Severity N - NO APPARENT INJURY		41 - Airbag NON-DEPLOYED		42 - Ejected NOT-EJECTED		44 <input type="checkbox"/> Medical Transport	
43 - Trapped/Extricated NOT-TRAPPED		92 - Pedestrian Location		92 - Pedestrian Action			
119 - What Driver Was Doing STOPPED-IN-TRAFFIC		120 - Traffic Control NO-CONTROL		62 - No. of Citations Issued			
64 - 1st Statute No.		64 - 2nd Statute No.		64 - 3rd Statute No.		64 - 4th Statute No.	
64 - 5th Statute No.							
122 - Driver Factors NOT-APPLICABLE							
88 - Driver or Pedestrian Cond APPEARED NORMAL		89 - Substance Presence UNKNOWN					
90 - Alcohol Test TEST NOT GIVEN		90 - Alcohol Content		91 - Drug Test TEST-NOT-GIVEN			

91 - Drugs Reported
124 - Highway Factors NOT-APPLICABLE

Vehicle

VEHICLE 01	21 - Unit Type TRUCK	Vehicle Type PICKUP/UTILITY-TRUCK				22 - Total Occupants 2
	56 - License Plate Number FC9679	57 - Plate Type LTK	58 - State WI	59 - Exp Year 2012	55 - Vehicle Identification Number 1FTSS34L84HA77448	
	50 - Year 2004	51 - Make FORD	52 - Model ECONOLINE	53 - Body Style VN	54 - Color WHI	100 - Skidmarks to Impact (Ft)
	94 - Vehicle Damage FRONT					
	95 - Extent Of Damage MODERATE	96 <input type="checkbox"/> Vehicle Towed Due To Damage		97 - Vehicle Removed By OPERATOR		
	123 - Vehicle Factors NOT-APPLICABLE					

Vehicle Owner

VEH OWNER 01	45 <input checked="" type="checkbox"/> Vehicle Owner Same As Operator					
	46 - Vehicle Owner Last Name BOYCE		46 - First Name RANDY		46 - Middle Initial P	46 - Suffix
	46 - Company Name					
	47 - Address Street & Number W2834 S COUNTY ROAD A				47 - PO Box	
	48 - City PINE RIVER		48 - State WI	48 - Zip Code 54965		49 - Telephone Number (920) 420-4430 EXT.

Insurance

INS 01	63 - Liability Insurance Company SOCIETY-INS-A-MUTUAL-CO		60 <input checked="" type="checkbox"/> Policy Holder Same As Owner
	61 - Policy Holder Last Name BOYCE		61 - Policy Holder First Name RANDY
	61 - Policy Holder Company		

School Bus

BUS 01	Bus Travelling to/from <input type="radio"/> To <input type="radio"/> From	School Name	Body Make	Seating Capacity
	School District Contracted With			

Operator/Pedestrian

Unit Status		81 - Most Harmful Event: Collision With MOTOR VEHICLE IN TRANSPORT		23 - Dir Of Travel NORTH	24 - Speed Limit N/A
36 - Operating as Classified D CLASS		37 - Endorsements		35 <input type="checkbox"/> Operating Commercial Motor Vehicle	
29 - Drivers License Number H1581736621700		30 - State WI	31 - Expiration Year 2017	34 - On Duty Accident	
25 - Operator/Pedestrian Last Name HUEBNER		25 - First Name DAVID		26 - Middle Initial M	25 - Suffix
32 - Date Of Birth 06/17/1966		33 - Sex MALE			

OPERATOR/PEDESTRIAN 02	26 - Address Street & Number 3416 W LARSEN RD				26 - PO Box	
	27 - City NEENAH		27 - State WI	27 - Zip Code 54956	28 - Telephone Number (920) 836-3046 EXT.	
	39 - Seat Position FRONT-SEAT-LEFT-SIDE-(MC/BIKE DRIVER, TRAIN CONDUCTOR)				40 - Safety Equipment NONE-USED-VEHICLE-DRIVER/OCCUPANT	
	38 - Injury Severity N - NO APPARENT INJURY		41 - Airbag NON-DEPLOYED		42 - Ejected NOT-EJECTED	
					44 <input type="checkbox"/> Medical Transport	
	43 - Trapped/Extricated NOT-TRAPPED		92 - Pedestrian Location		92 - Pedestrian Action	
	119 - What Driver Was Doing BACKING-MANEUVER		120 - Traffic Control NO-CONTROL		62 - No. of Citations Issued	
	64 - 1st Statute No.	64 - 2nd Statute No.	64 - 3rd Statute No.	64 - 4th Statute No.	64 - 5th Statute No.	
	122 - Driver Factors INATTENTIVE-DRIVING					
	88 - Driver or Pedestrian Cond APPEARED NORMAL		89 - Substance Presence UNKNOWN			
90 - Alcohol Test TEST NOT GIVEN		90 - Alcohol Content		91 - Drug Test TEST-NOT-GIVEN		
91 - Drugs Reported						
124 - Highway Factors NOT-APPLICABLE						

Vehicle

VEHICLE 02	21 - Unit Type TRUCK		Vehicle Type PICKUP/UTILITY-TRUCK			22 - Total Occupants 1
	56 - License Plate Number 82089	67 - Plate Type MUN	58 - State WI	59 - Exp Year	66 - Vehicle Identification Number 1FDRF3G80BEC36604	
	50 - Year 2011	51 - Make FORD	52 - Model F350 SUPER	53 - Body Style CAB	54 - Color WHI	100 - Skidmarks to Impact (Ft)
	94 - Vehicle Damage REAR					
	95 - Extent Of Damage VERY-MINOR		96 <input type="checkbox"/> Vehicle Towed Due To Damage		97 - Vehicle Removed By OPERATOR	
	123 - Vehicle Factors NOT-APPLICABLE					

Vehicle Owner

VEH OWNER 02	45 <input type="checkbox"/> Vehicle Owner Same As Operator					
	46 - Vehicle Owner Last Name		46 - First Name		46 - Middle Initial	46 - Suffix
						Date Of Birth
	46 - Company Name COUNTY OF WINNEBAGO					
	47 - Address Street & Number 901 W CTH Y			47 - PO Box		
48 - City OSHKOSH		48 - State WI	48 - Zip Code 54901		49 - Telephone Number (920) 236-7300 EXT.	

Insurance

INS 02	63 - Liability Insurance Company GOVERNMENT		60 <input type="checkbox"/> Policy Holder Same As Owner
	61 - Policy Holder Last Name	61 - Policy Holder First Name	
	61 - Policy Holder Company		

### School Bus

BUS 02	Bus Travelling to/from <input type="radio"/> To <input type="radio"/> From	School Name	Body Make	Seating Capacity
	School District Contracted With			

### Diagram and Narrative

DIAGRAM AND NARRATIVE	105 - PHOTOS BY
	BOYH VEH'S WERE IN LINE AT THE COUNTY LAND FILL AT THE GATE, VEH #2 NEEDED TO LEAVE LOOKED IN THE MIRRORS SAW NO ONE AND BACKED INTO VEH #1

### Officer Information

OFFICER INFORMATION	125 - Officer Last Name HILL		125 - First Name PHIL		125 - Middle Initial		131 - Officer ID 74	
	129 - Law Enforcement Agency No. 7055		130 - Law Enforcement Agency Name OSHKOSH POLICE DEPARTMENT					
	126 - Law Enforcement Agency Address Street & Number 420 JACKSON STREET							
	127 - City OSHKOSH		127 - State WI		127 - Zip Code 54903		128 - Telephone Number (920) 236-6700 EXT.	
	132 - Date Notified 08/30/2012		133 - Time Notified (Military Time) 0667		134 - Time Arrived (Military Time) 0712		135 - Date Of Report 08/30/2012	
	Agency Accident Number 12-30947		Police Number		19 - Special Study			
	18 - Agency Space 1W 2W							



**BERGSTROM**

JOSH NIGBOR  
Body Shop  
Assistant Manager

651-9470

**BERGSTROM** Oshkosh Body Shop

3660 Jackson Drive

Oshkosh, Wisconsin 54901

920-966-1166 Direct: 920-651-9470 • Fax: 920-235-8308

jnigbor@bergstromauto.com • www.oshkoshgm.com

BERGSTROM AUTOMOTIVE  
355 NORTH WASHBURN STREET  
OSHKOSH, WI. 54904  
PHONE: 920-235-1075 FAX: 920-235-8308  
FEDERAL TAX ID: 391547151

\*\*\* PRELIMINARY ESTIMATE \*\*\*

09/10/2012 03:34 PM

Owner

Owner: RANDY READY BUILDERS  
Address: W2834 S CTY RD.A  
City State Zip: Pine River, WI 54965

Work/Day: (920)420-4430  
FAX:

Inspection

Inspection Date: 09/10/2012 03:35 PM  
Primary Impact: Front

Inspection Type:  
Secondary Impact:

Appraiser Name: JOSHUA NIGBOR

Appraiser License #:

Repairer

Repairer: BERGSTROM BODYSHOP  
OSHKOSH  
Address: 3650 JACKSON DR (physical)  
355 N WASHBURN (billing)  
City State Zip: OSHKOSH, WI 54901  
Email: mslusarski@bergstromauto.com

Contact: MIKE SLUSARSKI  
Work/Day: (920)235-2202  
Home/Evening: (920)235-1075  
FAX: (920)235-8308

Vehicle

2004 Ford E-350 STD 2 DR Cargo Van Extended  
8cyl Gasoline 5.4  
4 Speed Automatic

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Refinish: Two-Stage

VIN: 1FTSS34L84HA77148  
Mileage Type: Actual  
Code: P6156D  
Int. Refinish: Two-Stage

Options

AM/FM Stereo	Air Conditioning	Anti-Lock Brakes
Dual Airbags	Engine Cover Console	Intermittent Wipers
Lighted Entry System	Power Brakes	Power Steering
Tilt Steering Wheel	Tinted Glass	Vinyl Seats

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
1	E	63	46	Grille Assembly	F8UZ8200BAA	\$127.20		INC	SM
2	E	35	46	Reinf,Grille Assembly	F7UZ8A284AA	\$113.00		2.2	SM
3	E	59	46	Door,Headlamp LT	2C2Z13064AAB	\$17.37		INC	SM

09/10/2012 03:43 PM

4	E	60	46	Door,Headlamp RT	2C2Z13064AAA	\$17.85	INC	SM
5	EP	49		Lamp,Side Marker LT	Replace PXN	\$21.00	INC	SM
6	E	83	46	Panel,Hood	2C2Z16612AA	\$372.17	1.0	SM
7	L	83	13	Panel,Hood	Refinish		4.9	RF
				2.6 Surface				
				1.0 Edge				
				0.6 Two-stage setup				
				0.7 Two-stage				
8	E	84		Hinge,Hood Panel LT	8C2Z16797A	\$32.28	0.2	SM
9	L	84		Hinge,Hood Panel LT	Refinish		0.2	RF
				0.2 Surface				
10	E	85		Hinge,Hood Panel RT	8C2Z16796A	\$32.28	0.2	SM
11	L	85		Hinge,Hood Panel RT	Refinish		0.2	RF
				0.2 Surface				
12	E	73	46	Panel,Radiator Supt	4C2Z16138AA	\$373.58	8.0	SM
13	L	73		Panel,Radiator Supt	Refinish		1.8	RF
				1.5 Surface				
				0.3 Two-stage				
14	N	977		A/C Evacuate & Recharg	Additional Labor		1.4	ME
15	I	105	07	Pnl Assembly,Inr Fndr LT	Repair		1.0*	SM
16	L	105		Pnl Assembly,Inr Fndr LT	Refinish		0.7	RF
				0.6 Surface				
				0.1 Two-stage				
17	I	106	07	Pnl Assembly,Inr Fndr RT	Repair		1.0*	SM
18	L	106		Pnl Assembly,Inr Fndr RT	Refinish		0.7	RF
				0.6 Surface				
				0.1 Two-stage				
19	I	103		Fender,Front LT	Repair		3.5*	SM
20	L	103		Fender,Front LT	Refinish		2.3	RF
				1.9 Surface				
				0.4 Two-stage				
21	BR	104		Fender,Front RT	Blend Refinish		1.2	RF
				0.8 Blend				
				0.4 Two-stage				
22	I	207		Door Shell,Front LT	Repair		2.0*	SM
23	L	207		Door Shell,Front LT	Refinish		2.5	RF
				2.1 Surface				
				0.4 Two-stage				
24	RI	249		W/Strip,Belt Outer LT	R & I Assembly		0.2	SM
25	RI	74		Mirror,Outer Standard LT	R & I Assembly		0.3	SM
26	RI	227		Handle,Front Door Otr LT	R & I Assembly		0.5	SM
27	EC	M14		Corrosion Protection	Replace Economy	\$5.00*		SM
28	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*		SM
29	I			ROUGH PULL	Repair		2.0*	FR*
				>> PULL FRONT END TO SQUARE				
30	SB			"RANDY" STICKER	Sublet Repair	\$35.00*		SM*
				>> SUBLET TO THE STRIPE GUY				

30 Items

MC Message

07 STRUCTURAL PART AS IDENTIFIED BY I-CAR  
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE  
46 PRINTABLE ALTERNATE PARTS COMPARE

Estimate Total & Entries

Gross Parts	\$1,085.73	
Other Parts	\$26.00	
Paint Materials	\$522.00	
Parts & Material Total		\$1,633.73
Tax on Parts & Material	@ 5.000%	\$81.69



Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$56.00	12.6	7.5	20.1	\$1,125.60
Mech/Elec (ME)	\$85.00		1.4	1.4	\$119.00
Frame (FR)	\$65.00		2.0	2.0	\$130.00
Refinish (RF)	\$56.00	14.5		14.5	\$812.00
Paint Materials	\$36.00				
Labor Total				38.0 Hours	\$2,186.60
Tax on Labor		@ 5.000%			\$109.33
Sublet Repairs					\$40.00
Tax on Sublet		@ 5.000%			\$2.00
Gross Total					\$4,053.35
Net Total					\$4,053.35

Alternate Parts Y/07/01/00/06/06 CUM 07/01/00/06/06 Zip Code: 54901 Audatex Host  
Recycled Parts NOT REQUESTED


Audatex Estimating 6.0.726 ES 09/10/2012 03:43 PM REL 6.0.726 DT 08/01/2012 DB 09/01/2012  
Copyright (C) 2011 Audatex North America, Inc.

3.0 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

#### Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2011 Audatex North America, Inc.  
Audatex Estimating is a trademark of Audatex North America, Inc.